ECS Configuration Change Request Page 1 of 1 Page(s) 1. Originator 2. Log Date: 3. CCR #: 4. Rev: Tel: 6. Rm #: 7. Dept. SED Byron V. Peters 01-0816 301/883-4077 2103 10/17/01 8. CCR Title: Install new STK Microcode in PVC for Testing Originator Signature/Date 12. Need Date: 10/25/01 10. Class 11. Type: **CCR** Byron V. Peters /s/ 10/17/01 Ш 13. Office Manager Signature/Date 14. Category of Change: 15. Priority: (If "Emergency" fill in Block 27). Update ECS Baseline Doc. Emergency Carolyn Whitaker /s/ 10/17/01 16. Documentation/Drawings Impacted: 17. Schedule 18. Cl(s) Affected: None -- will baseline with follow on CCR Impact: 21. Estimated Cost: 19. Release Affected by this Change: 20. Date due to Customer: None - Under 100K 22. Source Reference: □NCR (attach) ☐ Action Item ☐ Tech Ref. ☐ GSFC ☒ Other: STK release notes attached. 23. Problem: (use additional Sheets if necessary) A new release of STK microcode for the STK 9840 and 9940 tape drives that fixes spinup errors is available. 24. Proposed Solution: (use additional sheets if necessary) Have STK install the new microcode on the Powderhorn silos in the PVC. 25. Alternate Solution: (use additional sheets if necessary) N/A 26. Consequences if Change(s) are not approved: (use additional sheets if necessary) Continued problems with spinup errors 27. Justification for Emergency (If Block 15 is "Emergency"): This is an ongoing problem operationally that needs to be tested ASAP here at the PVC ☐ GSFC ☐LaRC ☐NSIDC ☐SMC ☐AK ☐JPL 28. Site(s) Affected: ☐EDF □EDC Other ☐ IDG Test Cell EOC 29. Board Comments: 30. Work Assigned To: 31. CCR Closed Date: 32. EDF/SCDV CCB Chair (Sign/Date): Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS Kevin Lange /s/ 10/17/01 ERB Randall I Miller /s/ 1022/01 Disapproved Withdraw Fwd/ESDIS ERB Disposition: Approved App/Com. 33. M&O CCB Chair (Sign/Date): Fwd/ECS 34. ECS CCB Chair (Sign/Date): Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS

CM01JA00 Revised 3/29/01 ECS/EDF/SCDV/M&O